ZMAX V5 QUICK LIST

Mod No.: ZMAX V5 Dimension: 130 (105) mm Weight: 183g

Certificate: RoHs,CE, FCC, PSE, FDA Material: stainless steel Thread:510 & ego

Color: tarnish Variable voltage:3.0V-6.0V Variable Wattage:3W-

15W

PRODUCT DESCRIPRION

1. SIGELEI ZMAX V5 gun metal is the newest design-fashionable look.

- 2. Can charge mobile and pad.
- 3. One button for 9 menus;
- 4.OLED shows the left battery, puffs and wattage/output voltage/resistance of th
- e atomizer/current together; showing the smoking time separately
- 5. Telescopic body, fitting for 18350/18650/18500/18490battery
- 6. Variable voltage/wattage(3.0V-6.0V,3W-15W)
- 7.RMS/MEAN option
- 8.4A output limit
- 9. Short-circuit protection
- 10. overcharging protection(for the charger)

Component of the Kit

Control Assembly:1pcs	Battery:18650+18350	CE4 atomizer:1pcs
Certificate:1pcs	Manual:1pcs	Ends Cap:1pcs

Operation of Zmax V5

- -Press 5 times continuously to turn on/off the mod.
- -Press 3 times to browse the menu when the screen has shut down.
- -Choose the menu, wait 2 seconds to get into it and set the item; 2 seconds are needed to get it set and another 2 seconds required to exit the menu.
- -The menu always starts from the first: OUT ON/OFF.

MENU OF ZMAX V5

The menu has 9 different functions:

1. OUT ON/OFF

Disabling the button

The device can be disabled to prevent from unwanted firing by selecting 'OUT OFF'. When 'OUT ON' is selected then the device will work normally and atomizer will fire.

2. VOLTAGE UP

Increase voltage/wattage

To increase the Voltage in 0.1 Volt increments from 3.0V to 6.0V, or power in 0.5 Watt increments from 3.0W to 15.0W. Select Voltage or Wattage setting in menu 7.

3. VOLTAGE DOWN

Reduce Voltage/Wattage

To reduce the Voltage in 0.1 Volt decrements from 6.0V to 3.0V, or power in 0.5 Watt decrements from 15.0W to 3.0W. Select Voltage or Wattage setting in menu 7.

4. BATTER VOLTAGE

Battery level indicator

To check the Voltage of your battery. A fully charged battery will have 4.2V. We recommend charging the battery when it falls to 3.3V. Zmax will switch off automatically when the battery level reaches 3. 1V.

5. LCD DISPLAY

Information to display

To select what the display shows you while the button is pressed:

Voltage: to display the output voltage Time: to display the time of each puff

Resistance: to display the resistance of atomizer

Current: to display the working current

6. LCD ON/OFF

Switch LCD on/off

When 'ON' is selected, the LCD will display your settings when the button is pressed. When "OFF" is selected, the LCD will not display your settings when the button is pressed.

7. POWER VOLTAGE

Select VV or VW

To choose between variable voltage and variable wattage.

8. RMS&MEAN

Select RMS or MEAN voltage.

9. Mobile Power

Connect the cellphone with the ZMAX V5 with a USB charger. Choose 'Mobile OUT ON', and press for 10 seconds and it will charge the cellphone. In this period, the LCD will show 'Warning! 'and 'No smoking'.

To stop charging, press for another 10 seconds and seperate the cellphone and ZMAX V₅. Please make sure you have set Mobile Out OFF after charging. Only in this mode can you smoke.

NOTES

- 1. Clean the thread after using in case of rusting and corrosion.
- 2. Do not reverse the battery in the tube.
- 3. Remember to turn off Zmax when not using.
- 4. Do not use the protected batteries.
- 5. Had better not put Zmax in your pocket. A hanger is recommended.